



International Bar Coding Systems & Consulting Inc.

Head Office: 1940 Barnes Street, Penticton, BC V2A 4C3
Ph: 250.493.3201 Fx: 250.493.3257

Office: 441 - 11th Avenue, Oroville, WA 98844
Ph: 800.661.5570, Fx: 801.760.2519



To program the POS-X XI3200 Barcode Scanners (corded and bluetooth) for Windward Software scan the following barcodes in sequence (start with Step 1 and end with Step 5):





Power Management Mode

Power after setting time:

.B017\$



1 min

.B018\$



3 min

.B019\$



5 min

.B020\$



10 min

1. Do not over charge the battery, Power charging time is about 4 hours.
2. Please keep the scanner under moderate temperatures.
3. Do not expose scanner to direct sunlight.
4. Please use standard power adaptor from POS-X to ensure warrantee.
5. Warrantee void if any other brand / model power adaptor used.

Note:

1. When scanner reaches time out period, the scanner will be shut down for power saving purpose.
2. If scanner shuts down, please pull the trigger again to activate.